## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,958,629 B2

Page 1 of 1

APPLICATION NO.: 10/769257

DATED

: October 25, 2005

INVENTOR(S)

: Sapumal Wijeratne

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On The Drawings

Figure 2

Reference numbers 212, 250, 252, 266, and 268 should be deleted.

Figure 3

Reference numbers 330 and 392 should be deleted.

Column 3

Lines 49-50, "...n2 160..." should read --...n2 164...--.

Column 4

Line 7, "...n2 160..." should read --...n2 164...--.

Line 11, "...transisters 264..." should read --...transisters 262-264...-.

Line 37, "...n1 264..." should read --...n2 264...-.

Column 5

Lines 41 and 46, "...internal node 274..." should read --...internal node 270...-.

Column 6

Lines 6 and 10, "...A2\_b 322..." should read --...A2\_b 332...--.

Lines 7 and 10, "...A2 320..." should read --...A2 330...--.

Column 7

Line 38, "...second large comprises..." should read --...second large signal comprises...-.

Signed and Sealed this

Twenty-ninth Day of May, 2007

JON W. DUDAS Director of the United States Patent and Trademark Office